



**DOGGER BANK
TEESSIDE A & B**

**March
2014**

Environmental Statement Chapter 24 Appendix D Walkover Photos

Application Reference: 6.24.4

Cover photograph: Indicative image showing installation of meteorological mast within the Dogger Bank Zone



Appendix D - Dogger Bank Teesside A & B – Walkover Photographs
28 November 2012



Plate 1 Perimeter bunds at Wilton Complex, located in the vicinity of Dogger Bank Teesside A & B converter stations site



Plate 2 Perimeter bunds at Wilton Complex, located in the vicinity of Dogger Bank Teesside A & B converter stations site



Plate 3 Perimeter bunds and standing water at Wilton Complex, located in the vicinity of Dogger Bank Teesside A & B converter stations site



Plate 4 Perimeter bunds at Wilton Complex, located in the vicinity of Dogger Bank Teesside A & B converter stations site



Plate 5 Drain at Wilton Complex, adjacent to Dogger Bank Teesside C & D converter stations site



Plate 6 Rogers Dikes, Thrushwood Farm, looking north



Plate 7 Rogers Dikes, Thrushwood Farm, looking south, taken during a period of heavy rain and high river levels



Plate 8 Open land west of railway line, looking north west



Plate 9 Railway line from Blacks Bridge, looking north



Plate 10 Agricultural fields, direction north east from Blacks Bridge



Plate 11 Approximate landfall location, looking south west inland